

TABLE OF CONTENTS

CHAPTER		PAGE
	EXECUTIVE SUMMARY	ES-1
1	INTRODUCTION	1-1
	1.1 Transportation Goals and Objectives	1-1
	1.2 Study Area	1-5
	1.3 Study Process	1-5
	1.4 Public Participation	1-5
	1.5 Study Team	1-6
2	EXISTING TRANSPORTATION	2-1
	2.1 Study Area Demographics	2-1
	2.2 Existing Land Use	2-2
	2.3 Bicycle Facilities	2-4
	2.4 Pedestrian Facilities	2-4
	2.5 Park and Ride Lots	2-5
	2.6 Public Transit	2-6
	2.7 Waterbury-Oxford Airport	2-6
	2.8 Goods Movement	2-7
	2.9 Current and Projected Transportation System Performance	2-7
	2.10 Safety Analysis	2-9
	2.11 Geometric Deficiencies	2-12
	2.12 Signage Deficiencies	2-16
	2.13 Structural Evaluation	2-16
	2.14 Highway Capacity Analysis	2-18
3	EXISTING ENVIRONMENTAL CONDITIONS	3-1
	3.1 Wetland and Surface Water Resources	3-1
	3.2 Floodplains	3-1
	3.3 Groundwater Resources	3-1
	3.4 Rare, Threatened, and Endangered Species	3-2
	3.5 Farmland Soils	3-2
	3.6 Noise Sensitive Areas	3-2
	3.7 Air Quality	3-3
	3.8 Environmental Risk Sites	3-3
	3.9 Important Fisheries and Wildlife Habitat	3-4
	3.10 Historic and Archaeological Resources	3-4
	3.11 Section 4(f) and Section 6(f) Resources	3-6
	3.12 Environmental Justice	3-6
	3.13 Commercially Important Natural Resources	3-7
	3.14 Visual/Aesthetic Resources	3-7
	3.15 Business Activity and Major Employers	3-8
	3.16 Park Lands, Management Areas and Camp Grounds	3-8
	3.17 Museums and Cultural Resources	3-9

(Continued)

TABLE OF CONTENTS (Cont'd)

CHAPTER		PAGE
4	ALTERNATIVES EVALUATION	4-1
	4.1 Level of Improvements	4-1
	4.2 Screening Methodology	4-1
	4.3 TA 1 – No Build (Existing and Committed)	4-2
	4.4 TA 2 – Transportation System Management, Transit Operations and Transportation Demand Management Transit Operations	4-2
	4.5 TA 3 – Freeway and Interchange Reconstruction	4-7
	4.6 Transportation Evaluation	4-13
	4.7 Environmental Evaluation	4-18
	4.8 Preliminary Construction Cost Estimates	4-19
	4.9 Preliminary Screening	4-19
5	REFINEMENT OF ALTERNATIVES	5-1
	5.1 Additional General Purpose Lane	5-1
	5.2 Intersection Operational Improvements	5-2
	5.3 Arterial Signal Coordination	5-10
	5.4 Interchange Reconstruction Modifications	5-11
	5.5 Directional and Wayfinding Signage Plan	5-17
	5.6 Waterbury Access Study	5-17
	5.7 Construction Cost Estimates	5-18
6	SUMMARY OF RECOMMENDATIONS AND ACTION PLAN	6-1
	6.1 Recommended Actions	6-1
	6.2 Next Steps	6-13
	APPENDIX	
	Written Comments Received	

TABULATIONS

TABLE NUMBER		PAGE
ES-1	Summary of Interchange 13 Recommendations	ES-7
ES-2	Summary of Interchange 14 Recommendations	ES-8
ES-3	Summary of Interchange 15 Recommendations	ES-10
ES-4	Summary of Interchange 16 Recommendations	ES-11
ES-5	Summary of Interchange 17 Recommendations	ES-13
ES-6	Summary of Interchange 18 Recommendations	ES-15
ES-7	Summary of Additional Recommendations	ES-17
1.1	Study Goals and Objectives	1-3
2.1	Population Change	2-1
2.2	Non-Agricultural Employment (Persons Employed) Change	2-2
2.3	I-84 Park and Ride Lots	2-5
2.4	1995-1997 SLOSS Locations on I-84	2-10
2.5	On-Ramp Assessment	2-14
2.6	Off-Ramp Assessment	2-15
2.7	Freeway Analysis Summary	2-19
2.8	Freeway Ramp Analysis Summary	2-20
2.9	Weaving Analysis Summary	2-21
2.10	Capacity Analysis Summary – Signalized Intersections	2-22
2.11	Capacity Analysis Summary – Unsignalized Intersections	2-23
3.1	Potential Noise Barrier Locations along I-84	3-3
3.2	Potential Environmental Risk Sites in the I-84 Corridor	3-4
3.3	Historic Resources in the Vicinity of I-84 West to East along the Corridor	3-5
3.4	Comparison of Environmental Justice Factors I-84 Needs Deficiencies	3-7
3.5	Preserved Open Space in the I-84 Study Area	3-9
4.1	TA 2: TSM, TDM and TO	4-3
4.2	Freeway Analysis Summary – Build Scenario (Eastbound Direction)	4-13
4.3	Freeway Analysis Summary – Build Scenario (Westbound Direction)	4-14
4.4	Freeway Ramp Analysis Summary	4-15
4.5	Intersection Analysis – Build Scenario	4-17
4.6	Ranking of Potential Environmental Impacts	4-20
5.1	TSM Improvements	5-2
5.2	Interchange 13 Deficiencies/Needs and Improvements	5-3
5.3	Interchange 14 Deficiencies/Needs and Improvements	5-4
5.4	Interchange 15 Deficiencies/Needs and Improvements	5-6
5.5	Interchange 16 Deficiencies/Needs and Improvements	5-9
5.6	Interchange 17 Deficiencies/Needs and Improvements	5-13
5.7	Interchange 18 Deficiencies/Needs and Improvements	5-14
5.8	Interchanges 19-21 Deficiencies/Needs and Improvements	5-18
5.9	Engineering Cost Estimate for Additional General Purpose Lane on I-84	5-20
5.10	Interchange Construction Costs	5-21
6.1	Summary of Interchange 13 Recommendations	6-2

(Continued)

TABULATIONS (Cont'd)

TABLE NUMBER		PAGE
6.2	Summary of Interchange 14 Recommendations	6-3
6.3	Summary of Interchange 15 Recommendations	6-5
6.4	Summary of Interchange 16 Recommendations	6-7
6.5	Summary of Interchange 17 Recommendations	6-9
6.6	Summary of Interchange 18 Recommendations	6-11
6.7	Summary of Additional Recommendations	6-13

ILLUSTRATIONS

FIGURE NUMBER		FOLLOWS PAGE
1.1	Study Area	1-6
2.1	Waterbury Trip Ends	2-2
2.2	Selected Peak Hour Volumes	2-8
2.3	I-84 LOS Westbound A.M. Peak Period	2-8
2.4	I-84 LOS Eastbound P.M. Peak Period	2-10
2.5	Signage Deficiencies Southbury and Oxford	2-16
2.6	Signage Deficiencies Middlebury and Waterbury	2-16
2.7	Condition of I-84 Structures	2-18
4.1	TA 2 – TDM/TSM/Transit Operations	4-2
4.2	TA 3 – Interchange Improvements	4-8
4.3	TA 3 – Additional General Purpose Lane	4-8
4.4	TA 3 – Additional General Purpose Lane – Detailed View	4-8
4.5	Interchange 19/20 Existing Conditions	4-12
4.6	Interchange 19/20 Potential Alternative	4-12
4.7	I-84 LOS Westbound A.M. Period	4-14
4.8	I-84 LOS Eastbound P.M. Period	4-14
5.1	Additional Lane Alternatives	5-2
5.2	Interchange 13 Improvements	5-4
5.3	Interchange 14 Improvements	5-4
5.4	View of Westbound Approach on Main Street South at South Britain Road Intersection	5-4
5.5	Interchange 15 Improvements	5-6
5.6	View of Northbound Approach on Main Street at Main Street/Route 6 Southbury Plaza Intersection	5-6
5.7	View of Southbury Plaza Driveway at the Main Street/Route 6 Southbury Plaza Intersection	5-6
5.8	Interchange 16 Improvements	5-10
5.9	View of Route 188 Northbound Approach at Route 188/Old Waterbury Road Intersection	5-10
5.10	Interchange 17 Improvements	5-12
5.11	View of Westbound Approach on the Route 64 at Route 63 and Route 64 Intersection	5-12
5.12	View of Route 64 with Limited Sight Distance and Rock Ledge on Both Sides of the Roadway	5-12
5.13	Interchange 18 Improvements	5-16
5.14	View of the Chase Parkway Bridge over I-84	5-16
5.15	View of the Chase Parkway EB Approach at Country Club Road and Chase Parkway Intersection	5-16
5.16	Downtown Waterbury Signage Plan	5-18